

STATE OF UTAH  
DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
Telephone: (801) 538-5340  
Fax: (801) 359-3940

ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. GENERAL INFORMATION

1. Report Time Period: From (mo./yr.) 1/92 To (mo./yr.) 12/92
2. DOGM File Number: M/021 / 004
3. Mine Name: Escalante Silver Mine
4. Mineral(s) Mined: None - Mine Closed
5. Legal Description (Location of Lands Affected):  
1/4, SE 1/4, Section 2, Township 36S, Range 17W  
1/4, 1/4, Section , Township , Range  
1/4, 1/4, Section , Township , Range
6. Name of Operator or Company: Hecla Mining Company

RECEIVED

JAN 15 1993

DIVISION OF  
OIL, GAS & MINING

Permanent Address: 6500 Mineral Drive  
Coeur d'Alene ID 83814

8. Company Representative (or designated operator):

Name: Gary R Gamble  
Title: Environmental Engineer  
Address: Box C-8000, 6500 Mineral Drive, CDA, ID 83814-1931  
Phone: (208) 769-4100

☒ Please check if any of the above information has changed since previous year.

II. MINING AND RECLAMATION

1. Was the mine active during the past year? Yes ☐ No ☒

2. If active, how much ore or mineral was mined? \_\_\_\_\_

3. How much new or additional acreage was affected during past year? None

4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

None  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

5. How much acreage was reclaimed during past year? None

6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

**RECEIVED**

JAN 15 1995

DIVISION OF  
COAL MINING

7. What is the total disturbed acreage at years end? 105
8. Briefly summarize mining and reclamation planned for the upcoming year.  
Plans for reclamation of tailings impoundment area still  
in regulatory review and revision process. Reclamation  
will proceed as per approved plan.

NOTE: Section III., "Additional Information" applies only to large mining operations.

III. ADDITIONAL INFORMATION

1. An updated surface facilities map should be attached if there have been significant changes since the previous map was submitted. N/A
2. Any monitoring results or other reports that are required under the terms of the approved notice of intention should also be attached. N/A

IV. SIGNATURE REQUIREMENT

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Gary R. Gamble

Title of Operator: Environmental Engineer

Signature of Operator: Gary R. Gamble

Date: January 12, 1993

jb  
MR-AR

RECEIVED

JAN 15 1993

DIVISION OF  
OIL, GAS & MINING



Waye

January 13, 1993


State of Utah  
Department of Natural Resources  
Division of Oil, Gas and Mining  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-5340

**RE: Annual Report of Mining Operations, DOGM File No. M/021/004**

Dear Sirs:

Enclosed you will find the Annual Report of Mining Operations for Hecla's Escalante Silver Mine.

Very truly yours,

  
Gary R. Gamble  
Environmental Engineer

enclosures

cc: Larry Drew  
George Wilhelm

RECEIVED

JAN 15 1993

DIVISION OF  
OIL GAS & MINING